

Summary of EPA review of Parcel G Trench Units Draft 10-16-2017

Number of TU's	% of Parcel G total
63	100%

Navy reviewed 63 total Trench Units to look for signs of potential falsification

20	32%
0	0%
43	68%

EPA reviewed the 43 Trench Units recommended for NFA

3	5%
0	0%
40	63%

Total Navy and EPA recommend for resampling

60	95%
----	-----

Trench Unit	EPA score
TU089	0
TU118	0
TU151	0
TU078	2
TU079	2
TU103	2
TU106	2
TU107	2
TU119	2
TU067	2
TU068	2
TU069	2
TU071	2
TU072	2
TU073	2
TU074	2
TU075	2
TU076	2
TU080	2
TU082	2
TU083	2
TU085	2
TU087	2
TU088	2
TU091	2
TU092	2
TU093	2

TU096	2
TU097	2
TU098	2
TU099	2
TU100	2
TU101	2
TU102	2
TU102	2
TU104	2
TU108	2
TU111	2
TU115	2
TU116	2
TU117	2
TU121	2
TU124	2
TU204	2

	Total trench units in Parcel G
<i>Units to look for signs of potential falsification</i>	
	Navy recommended confirmation sampling due to signs of potential falsification
	Navy recommended reanalysis of archived samples
	Navy recommended NFA = No further action due to signs of falsification, but potential further action due to uncertainty
	EPA score 0 = No specific findings of particular concern
	EPA Score 1 = Need further review
	EPA Score 2 = Need resampling before determination that the record supports ROD requirements met
<i>For resampling</i>	
	95% of total TU's now recommended for resampling and 0% need further evaluation
	Note: TU 66 and TU 70 the Navy recommended for partial re-sampling only. However, both are marked for full resampling due to suspect soil from the fill unit that was used to fill those TUs.

|

inty

|

